

SECRET

13 March 1962

MEMORANDUM FOR: Chief, Supply Division, Office of Logistics

REFERENCE : Memo from Chief, Supply Division to Chief, TSD
dated 7 March 1962, Subject as below

SUBJECT

25X1A

1. Major deficiencies noted in your recent testing at [REDACTED] 25X1A
indicate that the contractor neglected to insure that the [REDACTED] were 25X1A
waterproof during the reworking process.

2. Among two of the five units tested, it was noted that leakage
occurred around one of the screw holes in the plastic face plate. It is
not known where the other units leaked. It could have been around the
[REDACTED] base fittings as improper washers were used in this piece.

25X1A

3. This matter of leaking and the use of proper washers will be discussed
in detail with the contractor during the current week. After this
discussion a recommendation will be made as to procedures for checking and
reworking where necessary the units which fall within the lot tested recently.

25X1A

Chief
TSD/Engineering Branch

DD/P/TSD/[REDACTED] 25X1A ec

*15 ea shipped to
contractor approx 19 March 62
(BND)*

SECRET

OL 2 1489

ROUTING AND RECORD SHEET

SUBJECT: (Optional)

FROM:

NO.

DATE

TO: (Officer designation, room number, and building)

DATE

OFFICER'S INITIALS

COMMENTS (Number each comment to show from whom to whom. Draw a line across column after each comment.)

	DATE		OFFICER'S INITIALS
	RECEIVED	FORWARDED	
1. <i>C/Supply Division/α</i> <i>1000 King Sts & ~</i>			
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
13.			
14.			
15.			

MAR 16 1 15 PM '62

UL 2 1480

FORM 1 DEC 56

610 USE PREVIOUS EDITIONS



SECRET



CONFIDENTIAL



INTERNAL USE ONLY



UNCLASSIFIED

GPO 1961 : O-593644